

AERMOTOR

DEAN BENNETT SUPPLY CO

Toll Free : 800 - 621 - 4291

Repair Parts

Parts Orders Less than \$ 200	Net
Parts Orders \$ 200 thru \$ 500	-15% Disc
Parts Orders Over \$ 500	-20% Disc

4 - 30 - 08

Page 56

REPAIR PARTS FOR CURRENT MODEL #802 & OLDER MODEL #702 AERMOTOR WINDMILLS

Description	Part #	(X) 6 Ft	(A) 8 Ft	(B) 10 Ft	(D) 12 Ft	(E) 14 Ft	(F) 16 Ft
Vane Spring	28	\$ 19.00	\$ 24.00	\$ 44.00	\$ 76.00	\$ 126.00	\$ 173.00
Outer Band of Wheel	34	26.50	35.75	73.75	108.00	213.00	279.00
Inner Band of Wheel	35	11.50	22.00	33.50	57.50	78.25	119.00
Narrow U-Bolt for Vane	44	10.00	12.00	12.00	15.00	17.00	27.00
Wide U-Bolt for Vane	46	10.00	12.00	12.00	17.00	24.00	39.00
14' Long Wood Pump Pole	51	No Longer Furnished - Buy Locally					
Connector - Pump Pole to Well Rod	62	22.00	22.00	28.00	37.00	52.00	82.00
Set of Pump Pole Splice Straps	82	22.00	22.00	27.00	34.00	48.00	58.00
Sail w/sail tie #17	100	30.00	38.00	68.00	88.50	125.50	171.00
Sail Rib	101	6.00	8.00	11.00	15.00	19.00	28.00
#802 Domestic Pull Rod	171	57.25	60.50	82.50	145.25	262.00	430.00
#702 Import Pull Rod	FR171	53.00	57.00	78.25			
Furl Handle Assembly	243-1/2	41.00	41.00	58.00	81.00	87.00	129.00
Oil Ring	507	8.00	9.00	10.00	13.00	14.00	16.00
Pitman Guide w/#588 & 2-#508R	508	41.00	49.00	63.00	140.00	260.00	296.00
Pitman Guide Rivet	508R	1.00	2.00	3.00	4.00	5.00	6.00
Pivot Bolt for Tail Bone	510	20.00	23.00	37.00	57.00	83.00	118.00
Spring for Spout Washer	517	3.00	3.00	5.00	6.00	7.00	8.00
Oil Collector	520	11.00	12.00	14.00	16.00	25.00	35.00
Split Washer	521	9.00	10.00	12.00	14.00	18.00	21.00
Shaft for Guide Wheel w/Cotters	522	13.00	20.00	28.00	38.00	74.00	109.00
Guide Wheel	523	29.00	35.00	45.00	75.00	107.00	152.00
Furl Link w/Cotter Pin	527	8.00	9.00	14.00	16.00	22.00	27.00
Furl Arms w/Cotter Pins (pair)	528	23.00	30.00	36.00	59.00	69.00	86.00
Furl Arms w/Cotters (pair) Long	528-1/2	24.00	31.00	38.00	61.00	72.00	90.00
Furl Arms w/Cotters (pair) X-Long	528-3/4	N/A	33.00	40.00	63.00	74.00	93.00
Helmet w/hardware	560	169.50	185.00	213.50	288.25	485.00	556.00
Nut for 588	565	4.00	4.00	4.00	5.00	5.00	6.00
Steel Washer for Table	576	2.00	3.00	4.00	6.00	7.00	8.00
Locknut for Top of Mastpipe	578	9.00	14.00	22.00	32.00	44.00	51.00
Lockwasher for Top of Mastpipe	579	4.00	4.00	6.00	7.00	8.00	10.00
Vane Spring Holder	580	9.00	13.00	16.00	29.00	32.00	36.00
Tailbone Casting	585	35.00	42.00	74.00	87.00	118.00	148.00
Stud for Pitman Guide	588	5.00	5.00	5.00	8.00	9.00	11.00
Pump Rod Yoke w/Cotter Pin	608	48.00	52.00	66.00	110.00	154.00	228.00
Furl Lever Complete - 4 Post	609S	88.00	109.00	155.00	206.00	334.00	415.00
Pin for 608 Yoke	610	5.00	6.00	8.00	9.00	11.00	15.00
Upper Furl Ring w/o Arms	613-1/2	75.00	76.00	92.00	138.00	209.00	300.00
Lower Furl Ring 4 Post Split	614S	35.00	38.00	57.00	74.00	92.00	113.00
Bolt w/ Cotter Pin	622	5.00	6.00	8.00	11.00	13.00	14.00

PRICES SHOWN IN DARKER BOLD TYPE ARE NORMAL DENVER STOCK REPAIR PARTS

REPAIR PARTS QUALIFY FOR \$ 1,000.00 FREIGHT PREPAID ORDERS